

Select Language ▾

IBM Support

Search support or find a 

SCSI Terminator Verification

Technote (troubleshooting)

Problem(Abstract)

Incorrect SCSI Terminator usage causes LTO products to not appear on SCSI bus

Resolving the problem

The most common problem with not seeing LTO products on the SCSI bus is the wrong terminator being used. We have seen situations in the field where the wrap tool was used instead of the terminator. There is not an immediate distinction between the terminator or wrap tool because they both look the same, unless you have the newer wrap tool. The new wrap tool has a wrap around label that has printed on it "Wrap Tool". Otherwise, the only way to determine which part is being used is by examining the part number printed on them.

The following list shows part numbers for terminators and wrap tools.

SCSI	PN
LVD/SE	19P0874

HVD	61G8324
WRAP	PN
LVD/SE	19P0481
HVD	19P1213



Cross reference information

Segment	Product	Component	Platform	Version	Edition
Tape Storage	Tape Autoloaders	3581 Ultrium Tape Autoloader			
Tape Storage	Tape Libraries	3583 Ultrium Scalable Tape Library			
Tape Storage	Tape Libraries	3584 UltraScalable Tape Library			
Tape Storage	Tape Autoloaders	3581-2U Ultrium Tape Autoloader			
Tape Storage	Tape Libraries	3582 Ultrium Scalable Tape Library			
Tape Storage	Tape Libraries	TS3310 Tape Library			
Tape Storage	Tape Libraries	TS3100 and TS3200 Tape Libraries			
Tape Storage	Tape Libraries	TS3100 Tape Library Express			



Contact and feedback

Need support?



E-mail feedback to IBM support



1-800-IBM-7378 (USA)