



HP Support Center

[Insight Online](#)[Product Support](#) ▾[My IT Environment](#) ▾[Print](#) | [Rate this content](#)

SUPPORT COMMUNICATION - PRODUCT CHANGE NOTIFICATION

Document ID: c00700940**Version:** 4**NVIDIA Quadro FX 4500 Graphic Card - Video BIOS v 5.70.02.41.01 - PSG****Release Date:** 2006-06-12**Last Updated:** 2006-08-11

DETAILS OF CHANGE

- Printed Circuit Board (PCB) changed from NVIDIA design specification P347 to P348.
- Updated video BIOS to v 5.70.02.41.01.
- Part number changed to 394753-003.

COMPONENT VERSION

394753-003

SUPPORT URL

[Click here to go to the HP Workstation support site.](#)

REASON FOR CHANGE

- PCB change to support new memory.
- BIOS change to support new PCB.
- To ensure product availability.

IMPACT OF CHANGE

- BIOS will not be backward compatible to current board. Future BIOS updates will be provided that can determine board version and load correct BIOS version.
- No change to ID string or driver.

NOTE:

- **The Effective Date is normally the earliest date this change may be implemented in the factory.**
- **The Effective Date is subject to change.**
- **Customers who use "Golden" images or "locked" configurations should test with the changes listed in this PCN.**

DATE OF CHANGE

Effective Date: 2006-08-01

Hardware Platforms Affected: HP xw4300 Workstation, HP xw4400 Workstation, HP xw6400 Workstation, HP xw8200 Workstation, HP xw8400 Workstation, HP xw9300 Workstation, HP xw9400 Workstation

Components Affected: NVIDIA Quadro FX4500, 512MB, PCI-E Graphic Card

©Copyright 2006 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company shall not be liable for technical or editorial errors or omissions contained herein. The information provided is provided "as is" without warranty of any kind. To the extent permitted by law, neither HP or its affiliates, subcontractors or suppliers will be liable for incidental, special or consequential damages including downtime cost; lost profits; damages relating to the procurement of substitute products or services; or damages for loss of data, or software restoration. The information in this document is subject to change without notice. Hewlett-Packard Company and the names of Hewlett-Packard products referenced herein are trademarks of Hewlett-Packard Company in the United States and other countries. Other product and company names mentioned herein may be trademarks of their respective owners.

Provide feedback

Please rate the information on this page to help us improve our content. Thank you!

Was the information on this page helpful?

[Very helpful](#)

[Somewhat helpful](#)

[Not helpful](#)

United States

About HP

- Contact HP
- Careers
- Investor relations
- Sustainability
- Newsroom
- Accessibility

Ways to buy

- Shop online
- Store locator
- Call an HP rep
- Find a reseller
- Enterprise Store login
- Public sector purchasing

HP Partners

- HP Partner first program
- Partner portal

Support

- Download drivers
- Support & troubleshooting
- Forums
- Register your product
- Manage commercial support cases
- Authorized service providers
- Check repair status
- Training & certification

Stay connected

Sign up for news & offers



[Recalls](#) | [Product recycling](#) | [Site map](#) | [Privacy](#) | [Terms of Use](#) | [Cookies & ad choices](#) | [Limited warranty statement](#) | [Terms & conditions of sales & service](#)

HP has split into two companies. For enterprise products go to Hewlett Packard Enterprise.

© Copyright 2016 HP Development Company, L.P.