


Components

Connectors & Switches Definition



Function Switch Pin Definition

	SW 1	SW 2	SW 3	SW 4
ON	Fan1~5 Monitoring Enable (RM41616B)	System Alarm Temperature is 65°C	HDD Sequential Spin up Disable	Fan Monitoring Enable
OFF	Fan1~4 Monitoring Enable (RM21508B & RM31212B)	System Alarm Temperature is 55°C	HDD Sequential Spin up Enable	Fan Monitoring Disable